



Dominion

**DAM INSPECTION CHECKLIST
POSSUM POINT POWER STATION
POND ABC**

INSPECTION DATE: 5/26/15

WEATHER: Mostly Cloudy, 79°F

INSPECTED BY: D. West, K. Homza

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	1045 hrs. Standing water behind sandbags, and along perimeter of pond near road. Sandbags and rip rap in place.
Erosion	N	N	
Low Point, B dike*			
Flow	N	N	1047 hrs. No standing water. Sand bags and rip rap in place.
Erosion	N	N	
Outfall			
water surface El. (top of stoplogs to water)			1053 hrs. Standing water behind sand bags and concrete weir structure. Small amount of dripping at weir in the corners. Does not appear to be ^{flow at} discharge pipe. 49"

* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.): No rainfall events in last 72 hrs. Small amount of standing water at the base of the slope b/w A + B pond.

HT: 1428

LT: 0758

